

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

1492  
NNE  
> 1  
1.881 mi.  
9933 ft.

TOIV HOME  
914 1ST COURT  
BROOKLYN, NY

NY Spills S108637215  
N/A

Relative:  
Higher

Actual:  
22 ft.

SPILLS:

Name: TOIV HOME  
Address: 914 1ST COURT  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0701917 / 2007-06-26  
Facility ID: 0701917  
Facility Type: ER  
DER Facility ID: 330926  
Site ID: 381534  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2007-05-16  
Investigator: hrpatel  
Referred To: Not reported  
Reported to Dept: 2007-05-16  
CID: 444  
Water Affected: Not reported  
Spill Source: Private Dwelling  
Spill Notifier: Responsible Party  
  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2007-05-16  
Spill Record Last Update: 2007-06-26  
Spiller Name: LEA TOIV  
Spiller Company: TOIV HOME  
Spiller Address: 914 1ST COURT  
Spiller Company: 001  
Contact Name: LEA TOIV  
DEC Memo: "stain near the boiler - Petro inspected Petro will install a new suction line. Patel will visit the site today to talk to owner about digout. 05/17/07-Hiralkumar Patel. visited site on 05/16/07. met Joseph Toiv and Lea Toiv. Ms. Toiv showed oil stain on concrete near boiler where underground oil line comes out from ground. no odors in basement. oil company has disconnected supply line from tank. supply line runs about 40 ft underground along foundation wall. not sure if any more leak except one near boiler as stuff loaded along wall. asked Ms. Loiv to open stained concrete area and to remove any contaminated soil. suggest her to expose entire supply line to check any more leaks from it. Joseph Toiv 914 1st Court Brooklyn, NY 11223-3233 Ph. (718) 998-4959 Fax (718) 338-9594 letter sent to Mr. Toiv. letter faxed to MR. Toiv with list of cleanup contractors. 06/13/07-Hiralkumar Patel. received message from Ms. Toiv. left message for Ms. Toiv. received call from Ms. Toiv. ABC tank did cleanup at site. asked Ms. Toiv to submit report. she will ask ABC to submit a report. 06/15/07-Hiralkumar Patel. received message from Donna from ABC tank. she is waiting for analytical results for soil samples taken from site and will call once she gets it. 06/26/07-Hiralkumar Patel. received report from ABC Tank. ABC tank

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

broke area near boiler where stain was found and took endpoint  
sample. no contamination found in endpoint sample. case closed. NFA  
sent to Mr. Toiv. letter faxed to Mr. Toiv and Donna."

Remarks:

"LEAKING PIPE AND OIL ON BASEMETN AND WILL BE CLEANED UP TOMORROW"

All Materials:

Site ID: 381534  
Operable Unit ID: 1138982  
Operable Unit: 01  
Material ID: 2128986  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: Not reported  
Units: G  
Recovered: .00  
Oxygenate: Not reported